

Boat Entrance/Exit Assist Handle

Instructions

Part #: 1026446

Parts List			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	1026445	Wdmt Boat Entrance-Exit Assist Handle
-	1	1026447	Hardware Box
2	2	1001815	Cap Blue #14 - 2.0x2.0x2.0
3	2	1003821	Wdmt QC Leg Pocket
-	1	1026602	Bolt Bag
4	4	1001793	Nut Square 1/2-13 Brass
5	4	1002558	Set Screw 1/2-13 x 1.5 SS 304 Cup Point

Failure to follow instructions may result in personal injury and may invalidate the applicable warranty.

Step 1. Connect both QC leg pockets to your QC accessory connectors (sold separately) using the four carriage bolts and flange nuts included with your QC accessory connector.

Note: Two QC accessory connectors are required.

Step 2. Slide the leg pockets over the legs of the Wdmt Boat Entrance/Exit Assist Handle positioned as shown.

Step 3. Insert two 1/2 square nuts into the nut channel of each leg pocket and thread one 1/2 x 1-1/2 set screw into each square nut just enough to not fall out.

Step 4. Connect the assembly to the dock using the QC connect system. Adjust to desired height and tighten the 1/2 x 1-1/2 set screws. Place blue caps onto ends of the handle as shown.

<u>Dock Type</u>	<u>QC Accessory Connector</u>
	<u>Part Number</u>
RS4 Dock	1006706
RS7 Dock	1006708
TS9 Dock	1006730
Poly Dock	1006608

